

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Inspection Report

Permit Number:	C0070016
Inspection Type:	COMPLETE
Inspection Date:	Thursday, March 18, 2004
Start Date/Time:	03/18/2004 10:00:00 AM
End Date/Time:	03/18/2004 4:00:00 PM
Last Inspection:	Thursday, February 26, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny 65

InspectionID Report Number: 210

Accepted by: dhaddock

03/26/2004

Permitee: MOUNTAIN COAL CO
Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES
Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages	Mineral Ownership	Types of Operations		
180.00 Total Permitted	✓ Federal	✓ Underground		
34.88 Total Disturbed	☐ State	Surface		
Phase I	☐ County	Loadout		
Phase II	✓ Fee	Processing		
Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this site visit was to conduct a complete inspection of the Gordon Creek reclaimed site. The permit status is described under standard # 1.

Inspector's Signature:

Joe Helfrich, Environmental Scientist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

Utah Where ideas conn

Monday, March 22, 2004

Date

Permit Number: C0070016

Inspection Type: COMPLETE

Inspection Date: Thursday, March 18, 2004

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V		✓	
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	~			
11.	Contemporaneous Reclamation		~		
12.	Backfilling And Grading		V		
13.	Revegetation	✓		✓	
14.	Subsidence Control	V			
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing		✓		
16.b	Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		V		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	V		✓	
22.	Other				

Permit Number: C0070016
Inspection Type: COMPLETE

Inspection Date: Thursday, March 18, 2004

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The permit for this reclaimed site was renewed effective August 28, 1999. The five year permit renewal application is due on April 28, 2004. There is one amendment pending, #AM02A, (Rock Gabion removal) submitted on March 13, 2002. The TA contained one deficiency requiring the applicant to demonstrate that no additional contributions of suspended solids were occurring in the receiving stream channel and to prevent material damage outside the permit area. No samples have been taken to date. On May 22, 2003, the Division conducted a Phase One bond release inspection for the reclaimed area, and a Phase Three bond release inspection for the Sweets Pond area. Other agencies represented were BLM, Steve Faulk, and OSM, Mitch Rollings. Mountain Coal representatives included Dan Guy, Vicky Miller, and Chris Hansen. Bond release for both areas was approved October 6, 2003.

2. Signs and Markers

The signs located at the access at the end of the county road were in good repair and contained the required information.

3. Topsoil

South facing portions of the site that were bare showed no signs of erosion or soil loss.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The fourth quarter 2003 pond inspections for the 2, 7, & 8 Sediment Pond, Jacobs Pond, and Sweets pond indicated that the ponds were stable and showed no signs of structural weakness. The ponds were inspected on October 27, 2003. The south facing slopes were bare, the majority of the reclaimed site was covered with 1'-3' of snow.

4.d Hydrologic Balance: Water Monitoring

The DMR's were current through January 2004 reporting no discharge for those time periods. Hard copies of the fourth quarter monitoring data were reviewed. The UPDES permit is valid through April 30, 2008.

13. Revegetation

This year's growth has not started.

21. Bonding and Insurance

Liberty Mutual Insurance Company holds the \$641,443.00 bond. St. Paul Fire & Marine Insurance Company carries a \$500,000 general liability coverage that expires 07/31/2004.

Permit Number: C0070016 Inspection Continuation Sheet

Inspection Type: COMPLETE

Inspection Date: Thursday, March 18, 2004 Page 4 of 4